



Portal > Knowledgebase > Iridium > Extreme 9575 Handset > How-To > Iridium Extreme  
Firmware Update Version HL18005

---

## Iridium Extreme Firmware Update Version HL18005

David Jones - 2019-06-12 - in How-To

**Important notice:** This version of firmware is pending verification from BEAM Communications. If you are using a BEAM docking station product with the 9575 phone, please check back in a few weeks.

This update file contains the following benefits for the Iridium 9575 phone:

- Addressed an issue where channel assignments were inadvertently being discarded in some situations thereby improving overall handset performance.
- Modified battery charging algorithm to ensure compliance with battery specifications.
- Resolved an issue wherein when the user attempted to enter the SMS menu when the outbox on the SIM was full the handset would reboot.

[Please click here for the firmware file and installation instructions.](#)

**Note: The firmware update utility is not compatible with Mac OSX.**