



Portal > News > Announcements > Iridium Extreme Firmware HL17001 Pulled Back - August 28, 2017

---

## Iridium Extreme Firmware HL17001 Pulled Back - August 28, 2017

2017-08-25 - Lu Parente - 0 Comments - in Announcements



### Action Required - Iridium Extreme® Firmware HL17001 Pulled Back

Iridium has advised Roadpost that firmware version HL17001 for the Iridium Extreme 9575 handset has been pulled back from use. Handsets loaded with HL17001 will cease to work properly, never finding the network and should revert to firmware version HL15002.

Follow the instructions using the article below to identify your existing firmware version and return to HL15002.

<http://support.roadpost.com/kb/articles/iridium-extreme-firmware-update-version-hl15002-2>

Thank you for your co-operation and understanding.

*Roadpost Customer Care*