



[Portal](#) > [News](#) > [Announcements](#) > [Iridium 9555 Antenna Repair Notice - February 26, 2016](#)

Iridium 9555 Antenna Repair Notice - February 26, 2016

2016-02-26 - David Jones - in [Announcements](#)



Iridium 9555 Antenna Repair Notice

Iridium has informed Roadpost that antenna repairs can no longer be performed on certain models of the 9555. Iridium 9555 phones with the model number IRID0015XX (XX is a place holder for the last two characters) can only be replaced outright at the \$545 rate.

If you have an antenna repair request please email support@roadpost.com with the IMEI number and model number. The location of these numbers can be found in the example picture below.



Thank you for your understanding.

Roadpost Customer Care